

Samples of Vandalism and Rain Damage at the Cotuit Elementary School as of 1/24/2024

With ongoing vandalism and roof leaks at the School property, the damage is mounting. For example, it is no longer possible to walk through the corridors without crunching on broken glass underfoot, and dodging moldy ceiling tiles and insulation that has dropped to the floor. Below are samples of such damage seen during a walk-through 1/24/2024.

Rain-damaged ceiling tiles and overflowing rain-water buckets and floor puddles.



Vandalized windows:



Vandalized emergency lighting and lighting/heating equipment knocked down from walls, ceiling of the gym and kitchen, and corridors.



Graffiti painted on classroom floors:

