



COTUIT ELEMENTARY SCHOOL
DEMOLITION AND SITE RESTORATION

2/19/2026



Feasibility Study – Demolition Option


- Demolish existing building structure and site elements
- Restore site to a natural state

Overall Site Plan



0' 20' 40' 80' N ↗
February 19, 2026

Site Plan - Vegetation



0' 20' 40' 80' N
February 19, 2026

Vegetation - Shrub Understory




Vegetation - Trees



EVERGREEN TREES



Pinus rigida
Pitch pine



Pinus strobus
White pine

DECIDUOUS TREES



Red Maple
Acer rubrum



White Oak
Quercus alba



Red Oak
Quercus rubra



Black Oak
Quercus velutina